Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 8/11/2015, 8/12/2015	Man Days: 2
Inspection Unit: Ashmore Storage	
Location of Audit: Ashmore	
Exit Meeting Contact: Kevin Glaspy	
Inspection Type: Standard Inspection - Record Audit	
Pipeline Safety Representative(s): Charles Gribbins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Kevin Glaspy	Quality Assurance Consultant	(217) 820-4221

Gas System Operations	Status
Gas Transporter	Panhandle or Trunkline
Miles of Main	See Comment
General Comment:	•
10" main 3503 8" main 4961 6" main 8355 4" main 22513 3" main 280 2" main 9911	
Confirm Operator's Potential Impact Radius Calculations	See Comment
General Comment:	·
2.375" MAOP 175 PIR 21.68 ' 10% buffer 23.85'	

[192.517(a)][192.505,192.507,192.509,	192.511(c)] Are pressure test records being maintained for piping	Satisfactory
	TEST REQUIREMENTS	Status
General Comment: Customer notification is not applicable as no cust	omers are supplied by the storage field.	
[192.16(c)]	Customer Notification: Has the operator notified each customer after the customer first receives gas at a particular location?	Satisfactory
No safety related condition reports were required	in 2013 & 2014.	
General Comment:	10 working days after discovery?	
[191.25]	Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than	Satisfactory
No safety related condition reports were required	in 2013 & 2014.	
General Comment:	Did the operator report datety Related Conditions:	Satisfactory
No supplemental incidents reports were required [191.23(a)]	Did the operator report Safety Related Conditions?	Catiofastam
General Comment:	f . 0040 . 0044	
[191.15(b)]	Were there any supplemental incident reports when deemed necessary?	Satisfactory
No incidents occurred in the storage field that req	uired reporting per Part 191 requirements in 2013 or 2014.	
General Comment:		
[191.15(a)]	Was a DOT Incident Report Form F7100.2 submitted within 30 days after detection of an incident?	Satisfactory
No incidents occurred in the storage field that req	uire reporting per Part 191 requirements in 2013 or 2014.	
General Comment:		
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Satisfactory
Re	gulatory Reporting Records	Status
Staff reviewed the Annual report at the ICC Office		
General Comment:		Ganoraciony
Annual Report (Form 7100.2.1) reviewe	ed for the year:	Satisfactory
4.5" MAOP 175 PIR 41.08' 10% buffer 45.18' 6.625" MAOP 175 PIR 60.47 10% buffer 66.52' 8.625" MAOP 175 PIR 78.73 10% buffer 86.60' 10.75" MAOP 175 PIR 98.12 10% 107.94'		

	operating above 100 psig?	
General Comment:		
Staff reviewed pressure test charts that indicated that putesting was conducted in 2014.	ressure test and strength test were performed as required testing conducted in 201	3 and no pressure
[192.517(b)][192.511,192.509,192.513]	Are pressure test records being maintained for at least 5 years on piping operating below 100 psig?	Satisfactory
General Comment:	•	
No piping was installed in the storage field in 2013 or 20	014 that operates under 100 psig	
	UPRATING	Status
Category Comment:		
No uprating was performed in the Ashmore Storage field	d in 2013 or 2014.	
[192.555][192.555]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of 30% or more SMYS?	Not Applicable
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Not Applicable
	OPERATIONS	Status
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Not Checked
General Comment:	·	
The Operations and Maintenance Manual will be review	ved at the Pawnee Training Center at a later date.	
Has the operator conducted a review of the 0	Operator Qualification Plan once per yr/15 months?	Not Checked
General Comment:		
The operator qualification plan was not reviewed as par	t of this inspection. To be reviewed at the Pawnee Training Center at a later date.	
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Satisfactory
General Comment:	·	
Staff reviewed construction records and verified records	s, maps and operating history at the Ashmore Storage Field.	
[192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to determine the effectiveness of normal O&M procedures when deficiencies are found?	Satisfactory
General Comment:		
No deficiencies were identified in storage field procedur	es in 2013 or 2014. Storage field personnel are included in the Ameren Quality Ass	essment program.
[192.603(b)][192.605(c)(1)(i)]	Does the operator maintain documentation for responding to, investigating, and correcting the cause of unintended	Satisfactory

	closure of valves or shutdowns?	
General Comment:		
No unintended closure of valves occurred in 2013 or	r 2014.	
[192.603(b)][192.605(c)(1)(ii)]	Does the operator maintain documentation for responding to, investigating, and correcting the cause of increase or decrease in pressure or flow rate outside normal operating limits?	Satisfactory
General Comment:		
No increase or decrease in flows outside the normal	l operating limits 2013 or 2014.	
[192.603(b)][192.605(c)(1)(iii)]	Does the operator maintain documentation for responding to, investigating, and correcting the cause of loss of communications?	Satisfactory
General Comment:	<u> </u>	
No loss of communications occurred in 2013 & 2014	4.	
[192.603(b)][192.605(c)(1)(iv)]	Does the operator maintain documentation for responding to, investigating, and correcting the cause of operation of any safety device?	Satisfactory
General Comment:		
The operator has not had any operations of any safe	ety devices in 2013 or 2014.	
[192.603(b)][192.605(c)(1)(v)]	Does the operator maintain documentation for responding to, investigating, and correcting the cause of any other foreseeable malfunction of a component, deviation from normal operation, or personnel error which may result in a hazard to persons or property?	Satisfactory
General Comment:		
The operator had several commercial power losses	at the compressor station and several other alarms in 2013 and 2014.	
[192.603(b)][192.605(c)(2)]	Does the operator maintain documentation of checking variations from normal operation after abnormal operation has ended at sufficient critical locations in the system to determine continued integrity and safe operation?	Satisfactory
General Comment:	·	
No issues were identified after taking corrective acti	ons.	
[192.603(b)][192.605(c)(3)]	Does the operator maintain documentation of notifying responsible operator personnel when notice of an abnormal operation is received?	Satisfactory
General Comment:		
Ameren maintains documentation of notifications red Staff reviewed the following: Ashmore Abnormal Op		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.603(b)][192.605(c)(4)]	Does the operator maintain documentation for periodically	
	reviewing the response of operator personnel to determine	Catiofootomy
	the effectiveness of the procedures controlling abnormal operation and taking corrective action where deficiencies	Satisfactory
	are found?	
General Comment:		
Staff reviewed the actions taken during periods of abnor	rmal operations and no deficiencies were identified in 2013 or 2014.	
[192.603(b)][192.619,192.621,192.623]	Is the operator maintaining documentation verifying their	Satisfactory
	Maximum Allowable Operating Pressure(s)? (MAOP)	
General Comment:		
	rding the system MAOP. Maps are utilized to record the current MAOP of piping in t ng shall be tested for new installation and to ensure the current MAOP is maintained 385 psig.	
CONTINUING	G SURVEILLANCE RECORDS	Status
[192.709(c)][192.613(a)]	Has the operator reviewed continuing surveillance records	
	for class location changes, failures, leak history, corrosion,	Not Checked
	changes in cathodic protection, and other unusual operating and maintenance conditions?	
General Comment:	operating and maintenance container.	
Class location surveys are performed by Transmission	Integrity Group. These records will be reviewed during the Transmission Integrity De	partment audit.
		•
	S LOCATION CHANGE	Status
CLAS	S LOCATION CHANGE	
	S LOCATION CHANGE Does the operator maintain documentation when the class location changes for a segment of pipe operating at a	
CLAS: [192.709(c)][192.609]	S LOCATION CHANGE Does the operator maintain documentation when the class	Status
[192.709(c)][192.609] General Comment:	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS?	Status Satisfactory
[192.709(c)][192.609] General Comment:	S LOCATION CHANGE Does the operator maintain documentation when the class location changes for a segment of pipe operating at a	Status Satisfactory
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the storarip rap no longer exposed.	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS?	Status Satisfactory
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the storarip rap no longer exposed.	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS? ge field and it was patrolled. In 2014 the pipe was covered and rock shield put on it a	Status Satisfactory and then covered with
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the stora rip rap no longer exposed. DAMAGE Category Comment: Locates for the Ashmore Storage Field are performed by	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS? ge field and it was patrolled. In 2014 the pipe was covered and rock shield put on it a	Status Satisfactory and then covered with Status
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the stora rip rap no longer exposed. DAMAGE Category Comment: Locates for the Ashmore Storage Field are performed by	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS? The proof of the pipe was covered and rock shield put on it as the proof of	Status Satisfactory and then covered with Status
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the storarip rap no longer exposed. DAMAGE Category Comment: Locates for the Ashmore Storage Field are performed by reviewed during a separate audit. There were no damage	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS? The prevention of the pipe was covered and rock shield put on it as the prevention of the preve	Status Satisfactory and then covered with Status ion Group and are
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the storal rip rap no longer exposed. DAMAGE Category Comment: Locates for the Ashmore Storage Field are performed by reviewed during a separate audit. There were no damage [192.709(c)][191.17(a)] Has the number of damages increased or de	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS? The preventage of the storage field piping due to third party damages. Did the operator track the number of damages per 1000 locate requests for the previous years?	Status Satisfactory and then covered with Status ion Group and are Not Checked
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the storarip rap no longer exposed. DAMAGE Category Comment: Locates for the Ashmore Storage Field are performed by reviewed during a separate audit. There were no damage [192.709(c)][191.17(a)]	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS? The prevention of the pipe was covered and rock shield put on it as the prevention of the preve	Status Satisfactory and then covered with Status ion Group and are Not Checked
[192.709(c)][192.609] General Comment: In 2013 there was a pieces of exposed pipe in the storal rip rap no longer exposed. DAMAGE Category Comment: Locates for the Ashmore Storage Field are performed by reviewed during a separate audit. There were no damage [192.709(c)][191.17(a)] Has the number of damages increased or de	Does the operator maintain documentation when the class location changes for a segment of pipe operating at a hoop stress that is more than 40% SMYS? The prevention of the pipe was covered and rock shield put on it as the prevention of the prevention of the pipe was covered and rock shield put on it as the prevention of the preventio	Status Satisfactory and then covered with Status ion Group and are Not Checked Not Checked

AMEREN ILLINOIS COMPANY/8-13-2015

Does the operator have a Quality Assur facilities?	ance Program in place for monitoring the locating and marking of	Not Checked
Do pipeline operators include performance measures in facility locating contracts?		Not Checked
[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Not Checked
Has the Operator adopted applicable se	ection of the Common Ground Alliance Best Practices?	Not Checked
If no, were Common Ground Alliance B	est Practices discussed with Operator?	Not Checked
	EMERGENCY PLANS	Status
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Satisfactory
General Comment:		
Staff verified the latest version of the emergency	plan as July 2, 2014. The Storage Emergency Manual version dated 7-2-2014.	
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	Satisfactory
General Comment:		
Review).	ovided training on the emergency plan 1-23-2013 and 2-10-14 (Annual Emergency Plan al ovided training on the O&M Manual. January 2014 (Gas Storage O&M Change Review. 1-	-
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Satisfactory
General Comment:		
The operator did not report any emergencies at the 2014.	his location. No reviews of employee's activities were required due to no emergencies occ	urring in 2013 and
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Satisfactory
General Comment:		
Staff verified that a meeting was held with Ashmo	ore Storage in the form of NIPA and SIPA Meetings for 2013 and 2014.	
[192.603(b)][192.615(a)(3)]	Did the review of emergency response time intervals regarding odor/leak complaint documentation indicate adequate emergency response intervals were achieved?	Satisfactory
General Comment:		
The storage field will respond to leak compliant a	nd also the local operating center handles all leak complaints calls that may involve the sto	orage facilities.

[192.603(b)][192.615(a)(11)]	Has the operator maintained documentation of actions that were required to be taken by a controller during an emergency?	Satisfactory
General Comment:	•	
	n emergency as no conditions that met an emergency occurred at Ashmore Storage. Als personnel in a timely manner in 2014. These were compressor shutdowns due to loss	
	DDORIZATION OF GAS	Status
[192.709(c)][192.625(f)]	Where required, has the operator maintained documentation of odorant concentration level testing?	Satisfactory
General Comment:	-	
Odorant concentration level testing results are performed the storage field does put in odorant at the storage	ormed by the local operating centers. Records are not maintained by the Storage Field. field that feeds into the distribution system. "Odorant Inspection Report" for 2013 and 2	014.
[192.709(c)][192.625(e)]	Where required, has the operator maintained documentation of odorizer tank levels?	Satisfactory
General Comment:	·	
Staff reviewed records and verified that odorizer tar	nk levels were maintained as required.	
PATRO	DLLING & LEAKAGE SURVEY	Status
[192.709(c)][192.705]	Does the operator maintain documentation of a patrol program as required?	Satisfactory
General Comment:		
The patrol was done on 5/20/2013 and then 6/11/20 In 2013 they had a section of exposed pipe along the and then put rip rap over this area and eliminated the	ne patrolled area, but in 2014 the operator noted that they have lowered the pipe put roc	ck shield over the pipe
[192.709(c)][192.706]	Does the operator maintain documentation of leakage survey(s) performed on a transmission pipeline?	Satisfactory
General Comment:	·	
Leak surveys were performed 5-22-24-2013 and the	en again in 6-11-14 with no leaks being indicated during either survey.	
ABANDONMENT or DI	EACTIVATION of FACILITIES PROCEDURES	Status
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected from all sources and supplies of gas, and purged of gas?	Not Applicable
General Comment:	·	
The operator did not have any abandoned pipelines	s in the storage field.	
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and	Not Applicable

	supplies of gas; purged of gas?	
General Comment:	2411 22 2 3427 2 342	
Abandoned piping was maintained on maps in the ass	ociated work packets.	
[192.603(b)][192.727(e)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging?	Satisfactory
General Comment:		
The operator procedures called for using a Sensit Gold	d to monitor the gas air mixture coming from the purge stack	
[192.727(g)][192.727(g)]	Did the operator maintain documentation for each abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable
General Comment:		
There is no commercially navigable waterways in the A	Ashmore Storage Field Area.	
COI	MPRESSOR STATION	Status
[192.709(c)][192.731(a)]	Has the operator maintained documentation of the compressor station relief devices at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff reviewed the following records: Compressor relies	f Valves Annual Inspection. 11-15-2013 and 11-01-2014	
[192.709(c)][192.731(c)]	Has the operator maintained documentation compressor station emergency shutdown at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff reviewed the following document Storage Field Fi emergency shutdown of the compressor's. 11/2/21/201	ire & Gas Detection Alarm Inspection and verified that the operator had completed th 13 & 10/20/2014	ne compressor station
Storage Field Fire Detection Alarm Inspection Jan/3/20	013 & 11/18/20133/31/14 & 7/2/14	
[192.709(c)][192.736(c)]	Has the operator maintained documentation of the compressor stations – detection and alarms?	Satisfactory
General Comment:		
Staff reviewed the following document for verification of November 2013 and October 2014.	of compressor stations detection and alarms: Ashmore Gas Storage Field Critical Ala	rm Inspection
PRESSURE	LIMITING AND REGULATION	Status
Category Comment:		
The operator does not have any pressure regulating st	tation at this storage field.	
[192.709(c)][192.739(a)]	Is the operator inspecting and testing the pressure limiting and regulating stations at a minimum of 1 per year/15 months?	Not Applicable

[192.709(c)][192.743(a)]	Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months?	Not Applicable
[192.709(c)][192.743(b)]	If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months?	Not Applicable
[192.709(c)][192.743(a),192.743(b),192.195(b)(2)]	Is overpressure protection provided by the supplier pipeline downstream of the take point?	Not Applicable
[192.709(c)][192.743(a)]	If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Not Applicable
VALVE	MAINTENANCE	Status
[192.709(c)][192.745(a),192.745(b)]	Did the operator inspect and partially operate transmission valves that might be required during any emergency at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff verified that valves associated within the storage field were	e inspected as required.	
[192.709(c)][192.749]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
There are no vaults in the transmission system that meets the 2	200 cubic foot requirements	
[192.709(c)][192.179]	Are transmission line valves being installed as required of 192.179?	Satisfactory
General Comment:		
The operator has not installed any valves that required to be pla	aced at certain distances.	
[192.709(b)][192.745(b)]	Did the operator take prompt remedial action to correct any valve found inoperable, unless an alternative valve was designated?	Satisfactory
General Comment:		
The operator did not have any valves that were found to be inop	perable during the inspection cycle for 2013 or 2014	
Investiga	ation Of Failures	Status
[192.709(c)][192.617]	Did the operator experience accidents or failures requiring analysis?	Satisfactory
General Comment:		
General Comment: The operator did not experience any accidents or failures requires.	ring analysis in 2013 or 2014.	
The operator did not experience any accidents or failures requir	ring analysis in 2013 or 2014.	Status

	welding procedure?	
General Comment:		
	ed at the Ashmore Storage Field for project pipe. Welding Procedure ENE-Ameren-002 Re 5L grades or greater than X42 thru X60, ASTM Grade Y-42 thruY-60	ev 2 Weld: S6070.
[192.603(b)][192.227,192.229]	Does the operator have documentation of welder qualification documentation as required?	Satisfactory
General Comment:	·	
The following welder's documents were reviewed	Rick Delong, Tim Blackburn, and Keil Peebles these were 2013 records, No welding was	conducted in 2014.
[192.807]	Does the operator have documentation of welder OQ records?	Satisfactory
General Comment:		
Staff reviewed the Operator Qualification for Keil	Peedles, Tim Blackburn, Rick Delong	
[192.709][192.243(b)(2)]	Does the operator have documentation of NDT personnel qualification as required?	Satisfactory
General Comment:		
Staff reviewed the NDT qualification for the follow Robert Doyal-Magnetic Partial, Liquid Penetrant, Andrew Graves-Magnetic Particle, Liquid Penetra	and Ultrasonic	
[192.709][192.243(f)]	Does the operator have documentation of NDT testing performed?	Satisfactory
General Comment:		
Staff reviewed the weld test reports for NDT testin during the NDT.	ng performed in 2013 there was not any welding performed in 2014, there were no cut out	or failures found
CORF	ROSION CONTROL RECORDS	Status
[192.491(a)][192.491(a)]	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system	Satisfactory
[192.491][192.459]	Has the operator maintained documentation of examination when buried pipe was exposed?	Satisfactory
General Comment:		
Staff reviewed buried pipe examination reports fill in 2014.	led out during construction projects. No issues were reported in 2013. There has not been	any pipeline exposed
[192.491][192.465(a)]	Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100 feet at a minimum of 10% annually?	Satisfactory
General Comment:	<u> </u>	
Staff reviewed 30 pipe-to-soil readings for the sto	rage area, readings all were found to be in compliance with85 volt criteria.	

[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not	Satisfactory
No test points were identified needing corrective action.		
General Comment:		
[192.491][192.471]	Has the operator maintained documentation of corrective actions taken when a test lead is no longer electrically conductive?	Satisfactory
The Ashmore Storage Field has 30 test point on its system.		
General Comment:		
[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic protection?	Satisfactory
There are no casings in the Ashmore storage field 2013 and 20	14.	
[192.491][192.467(a),192.467(c),192.467(d)] General Comment:	Has the operator maintained documentation of inspections or tests for electrical isolation including casings?	Not Applicable
General Comment: There are no unprotected pipelines in the Ashmore Storage Fie		
[192.491][192.465(e)]	Has the operator maintained documentation of unprotected pipeline surveys, inspections, or tests at a minimum of 3 years/39 months?	Not Applicable
General Comment: No corrective actions were required due to the cathodic survey	preformed in 2013 and 2014.	
[192.491][192.465(d)]	Has the operator taken prompt remedial actions to correct any deficiencies indicated by the monitoring?	Satisfactory
There are no bond on the storage field critical or non-critical.		
General Comment:		
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Not Applicable
Records where verified indicating that the rectifier were inspected rectifiers on a monthly basis.	ed as required by this section. At the Ashmore storage field they have been	inspecting the
General Comment:		
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Satisfactory

	affecting adjacent underground metallic structures?			
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion due to transportation of corrosive gas?	Satisfactory		
General Comment:				
The operator has not encountered any internal corrosion	problems in 2013 and 2014.			
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Satisfactory		
General Comment:				
Staff reviewed Buried Pipe Examination report and noted	that internal corrosion pipe conditions.			
[192.491]	Has the operator maintained documentation of written procedures supported by as-built drawings or other construction records?	Satisfactory		
General Comment:	·			
Staff reviewed as-built drawings of new installed pipe in 2	2013. There was not any pipe installed in 2014.			
[192.491][192.477]	Has the operator maintained documentation of internal corrosion coupon monitoring at a minimum of 2 per year/ 7 1/2 months?	Satisfactory		
General Comment:				
Ashmore storage does not use corrosion coupons at Ash	more storage, but does use a corrosion probe.			
[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory		
General Comment:	·			
Ameren has a waiver to conduct Atmospheric corrosion c survey.	during the leak survey cycle. No issues were identified during the 2013 and 2014 at	tmospheric corrosion		
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/ 39 months?	Satisfactory		
General Comment:				
Ameren has a waiver to conduct Atmospheric corrosion of survey.	during the leak survey cycle. No issues were identified during the 2013 and 2014 at	mospheric corrosion		
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation demonstrating that pipe removed due to external corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	Satisfactory		
General Comment:				
No piping was removed due to external corrosion in 2013 and 2014.				

TRAINING - 83 IL ADM. CODE 520		Status		
[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Satisfactory		
General Comment:				
Staff reviewed training documents Ameren Brands Training Module 1, 2, & 3 Safety Training nine subjects were listed in the records inspected. Staff reviewed the Ameren Operator Qualification Employee Summary Sheet to verify the training requirements.				
[520.10(a) (2)]	Do training records include verbal instruction and/or on the job training for each job classification?	Not Checked		
General Comment:				
These records will be required to be checked at the Pawnee Training Center at a later date.				
[520.10(b)]	Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Applicable		
General Comment:				
This is a public utility				
[520.10(a)(5)]	Are procedures periodically updated to include new materials, new methods of operation and installation, and changes in general procedures?	Satisfactory		
General Comment:				
Staff reviewed sections of the Operation and maintenance manual.				